

# CAUTION

## HORIZONTAL MILLING MACHINE

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Beware of moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Securely clamp workpiece to table.
- Use spring-loaded operational handles on machines with power-fed tables.
- Cover and store all unused cutters.
- Use “inch” stroke control mode for setup purposes.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owner’s operation manual.

Note: Immediately report all machinery malfunctions to management.